



SAFETY RECALL

Certain Milwaukee 15 Amp Grinders 6086-20, 6088-20, 6089-20

MILWAUKEE ELECTRIC TOOL CORPORATION IN COOPERATION WITH THE U.S. CONSUMER PRODUCT SAFETY COMMISSION (CPSC), IS VOLUNTARILY RECALLING CERTAIN MILWAUKEE 15 AMP GRINDERS. THESE GRINDERS CONTAIN A SWITCH THAT MAY STICK IN THE "ON" POSITION, WHICH COULD RESULT IN OPERATOR INJURY. THERE HAVE BEEN NO REPORTED INJURIES, HOWEVER THE POTENTIAL DOES EXIST. IMMEDIATE CORRECTIVE ACTION IS REQUIRED.

GRINDERS INCLUDED IN THIS RECALL HAVE CATALOG NUMBERS 6086-20, 6088-20, AND 6089-20 ON THE NAMEPLATE.

6086-20


9" 6000 RPM
Serial Prefix 991A and 991B only

6088-20

7" 6000 RPM
Serial Prefix 994A and 994B only

6089-20

9" 6000 RPM
Serial Prefix 992A only



IF THE NAMEPLATE HAS AN "X" STAMPED OR ETCHED ON IT NEXT TO THE SERIAL NUMBER, THE TOOL HAS BEEN REPAIRED.



IF YOU HAVE ONE OF THE GRINDERS, STOP USING IT IMMEDIATELY AND RETURN IT TO THE NEAREST MILWAUKEE FACTORY SERVICE CENTER OR MILWAUKEE AUTHORIZED POWER TOOL SERVICE STATION FOR REPAIR AT NO CHARGE. FOR ASSISTANCE IN LOCATING YOUR NEAREST FACILITY, CALL MILWAUKEE TOLL FREE AT:

1-800-414-6527

Monday – Friday, 6:00 a.m. – 6:30 p.m.– Central Time or

METProductSupport@mil-elect-tool.com

IF IT IS NECESSARY TO SHIP YOUR GRINDER, WE RECOMMEND THAT RETURNS BE MADE VIA FED-X GROUND. MILWAUKEE WILL REIMBURSE TOOL OWNERS FOR THIS EXPENSE. PLEASE NO UPS OR FED-X C.O.D. RETURNS FOR SHIPPING CHARGES.



MILWAUKEE ELECTRIC TOOL CORPORATION

www.heavydutytool.com

Issue Date: November 2002

Post Until: March 2003